S-210 Carrigan Farm Near Dublin Private

The Carrigan Farmhouse is a badly deteriorated second quarter of the 19th-century dwelling with Greek Revival interior woodwork. Circular sawn roof members, cut nails and riven oak lath suggest a c.1840-1850 building date. The house was previously three sections, descending in height. The shortest section has been removed, and the center section has lost its roof.

This 100-acre farm, located on the north side of Mitchell Road, has been known in past years as the "Carrigan Farm" or the "Punch Johnson" farm.

Maryland Historical Trust State Historic Sites Inventory Form

Magi No. 2002105435

DOE __yes __no

1. Nan	ne (indicate pr	referred name)		
historic Car	rigan Farm			
and/or common				
2. Loca	<u>ation</u>			
street & number	North Side of M	itchell Road		not for publication
city, town	Dublin	X vicinity of	congressional district	First
state Maryla	and	county	Somerset	
3. Clas	sification			
Category districtX building(s) structure site object	Ownership public private both Public Acquisition in process being considered not_applicable	Status occupied unoccupied work in progress Accessible yes: restricted yes: unrestricted no	Present Use agriculture commercial educational entertainment government industrial military	museum park X private residence religious scientific transportation other:
4. Own	er of Prope	rty (give names ar	d mailing addresse	s of <u>all</u> owners)
name James	s Porter			
street & number			telephone n	o.: 651 - 0343
city, town Pri	incess Anne	state	and zip code Md	21853
		al Descriptio		
		rset Clerk of Court		liber
street & number	Somerset County (Courthouse		folio
city, town Pr	cincess Anne		state	Md 21853
6. Repr	resentation	in Existing	Historical Surv	eys
itie				
date			federal state	e county locai
pository for su	rvey records			
ity, town			state	
-				

	December	
<i>1</i> .	Description	

Survey No. 5-210

Condition excellentX deteriorated good ruins fair unexposed	Check one unaltered X altered	Check one X original site moved date of move	
---	-------------------------------	--	--

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The Carrigan Farm is located on the north side of Mitchell Road, .4 of a mile east of Arden Station Road. This Mundred-acre farm is bordered on the north and west by branches of Kings Creek. The farmhouse faces north with the gable running east/west.

This c. 1840-1850 two-story side hall/parlor mortise and tenon frame house has a slightly shorter two-story, two-bay section to the east. The weatherboard frame house is supported by a brick pier foundation and covered by a medium pitched sheet tin roof.

The south elevation of the main house is three bays across with a two-panel door in the east bay. A three-light transom tops the door opening and 6/6 sash windows fill the remaining first and second floor openings. The boxed cornice is presently exposed.

The west gable end of the main block has an exterior 6:1 common bond brick chimney with corbelled shoulders at the second floor height. A layer of imitation brick asphalt siding partially covers the west gable end. Two small attic window openings flank the stack.

The south side of the main house is similar to the three-bay main elevation with a door opening in the east bay and 6/6 sash in the remaining openings.

The west gable end of the main house is largely covered by the slightly shorter two-story, two-bay addition. The north side has a two-panel door opening in the west bay, and 6/6 sash windows occupy the three remaining openings. The roof has fallen in, and the east end is badly deteriorated.

Inside the main house, the walls are plastered with riven oak lath fastened by cutnails. A dog-leg stair rises in the southeast corner. A slender square newer post a square balusters support a circular-profile handrail. A two-panel Greek Revival door framed by a fluted surround with corner blocks. The door opens into a nearly square parlor with end wall hearth. The plain post and lintel mantel has been removed from its original location.

The second floor is divided into a bedroom and a small room at the head of the stairs. The attic stair is located in this small room. A one-panel door encloses the small stairway. The bedroom is simply finished with lath and plaster. A plain post and lintel mantel survives on the end wall.

The first floor room of the kitchen wing has a large cooking hearth as well as an adjacent winder stair. The second floor is inaccessible due to the collapsed roof.

0. 3	ngnincance	Survey No.	2-210
Period	1499 archeology-historic conservation1599 agriculture economics1699 _X_ architecture education1799 art engineering1899 commerce exploration/settlements	Jandscape architectur Law Literature Literatury Law Literature Law Literature	science sculpture social/ humanitarian theater
Specific	dates Builder/Architect		
check:	Applicable Criteria: _A _B _C _D and/or Applicable Exception: _A _B _C _D	E F G	
	Level of Significance:nationalstate		
Prepare support	both a summary paragraph of significance and	l a general statement	of history and

The Carrigan farmhouse is a badly deteriorated second quarter of the 19th-century farmhouse with Greet Levivial interior woodwork. Circular sawn roof members, cut nails and riven oak lath suggest a c. 1840-1850 date of construction. The house was previously three sections, descending in height. The shortest section has been removed and the center section has lost its roof.

This 100-acre farm has been known in past years as the "Carrigan farm" or the "Punch Johnson farm", but little move information is available at the moment.

9. Major Bibliographical References

10. Geographic	al Data			
Acreage of nominated property Quadrangle name UTM References do NOT comple			Quadrangle scale	
Zone Easting North	ing	B Zone	e Easting Northing	
C		D F H		<u> </u>
Verbal boundary description and	justification	·		
List all states and counties for p	code	rlapping state or county	r county boundaries	
state	code	county	code	•
11. Form Prepa	red By	-		
name/title Paul Touart - Arc	chitectural	Historian		
organization Somerset County	y Historical	Trust	date 5/7/84	<u>-</u>
street & number 424 N. Some	rset Ave.		telephone 651-1094 (Home)	
city or town Princess Anne		·····	state _{Md} . 21853	

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust

Shaw House

21 State Circle

Annapolis, Maryland 21401

(301) 269-2438





Carrigan Farm
Near Wellington, Somerset County
North Elevation
5/84 Paul Touart
Neg./ Maryland Historic Trust



Carrigan Farm
North Elevation
Near Wellington, Somerset County
5/84 Paul Touart
Neg./ Maryland Historic Trust



Carrigan Farm
Near Wellington, Somerset CountyNorthwest Elevation
5/84 Paul Touart
Neg./ Maryland Historic Trust



Carrigan Farm
2nd Floor Mantel
Near Wellington, Somerset County
5/84 Paul Touart
Neg./ Maryland Historic Trust



Carrigan Farm
Parlor Door
Near Wellington, Somerset County
5/84 Paul Touart
Neg./ Maryland Historic Trust



Carrigan Farm
West Gable End
Near Wellington, Somerset County
5/84 Paul Touart
Neg./ Maryland Historic Trust



Carrigan Farm Attic Door Near Wellington, Somerset County 5/84 Paul Touart Neg./ Maryland Historic Trust